



Hydraulic Artist Bench Repair Instructions

Check all rubber hoses. If any need replacing, they are surgical tubing wrapped with nylon. If you cannot purchase locally Jansen will supply correct tubing.

Remove valve core with a valve-core remover. If you don't have one, they may be purchased at an auto-parts store for about \$1.00.

Turn bench right-side-up to drain any fluid which might be in tank.

Put in 10 oz. liquid.

Mix 8 oz. tap water (not distilled) plus 2 oz. Prestone (or other radiator antifreeze) as rust inhibitor.

Replace valve core.

Very slowly pressurize to 55 psi. Use a bicycle pump, not a high-pressure air pump.

Install valve stem cap.

Operate lift system. It may take 3 or 4 attempts to get everything circulating and moving again.